




HAZARDOUS CLASSIFICATIONS



**CLASS I DIVISION 2 :
MAXIMUM TEMPERATURES**

°C	°F	T#	°C	°F	T#
450	842	T1	180	356	T3A
300	576	T2	165	329	T3B
280	536	T2A	160	320	T3C
260	500	T2B	135	275	T4
230	446	T2C	120	248	T4A
215	419	T2D	100	212	T5
200	392	T3	85	185	T6

CLASS II

SKIN TEMPERATURE OF DEVICES NOT SUBJECT TO OVERLOADING SHALL NOT EXCEED 329 °F (165 °C). MOTOR TRANSFORMERS AND OTHER EQUIPMENT SUBJECT TO OVERLOADING SHALL NOT HAVE SKIN TEMPERATURE OVER 248 °F (120 °C).